

TASK LIST - PC1106 masonry CMU Repairs, Bartow RAD

Primary	Site	Trade Description	Deficiency	Solution	Addr Street	Location Notes	Qty	Unit
A.3.2.9.03 Repair CMU Walls	481170	CMU - Add Course(s)	Erosion	Add 1 course of blocks	301 Collins	Driveway right side	24	Lin Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - Add Course(s)	Erosion	Add 1 course	309 Collins	Front porch	24	Lin Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - Add Course(s)	erosion		316 Collins	Front porch	10	Lin Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - Add Course(s)	Erosion	Add 1 course of block	745 Fredricks	N/E corner close to Williams gate	40	Lin Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - Add Course(s)	Erosion over top of wall	Add one course	Melissa	Melissa wall rear of collins	300	Lin Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - Crack Chase & Grout	Crack chase and fill		308 Collins		45	Lin Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - Crack Chase & Grout	Crack chase and fill		Dolph	Retaining wall between dolph and fredricks	200	Lin Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - Crack Chase & Grout	Crack chase and tuck point	Approx 3 ft high. Qty is the entire length of	Dolph	Retaining wall between Powell and dolph	198	Lin Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - Crack Chase & Grout	Cracks, spalling		745 Fredricks	SE Street corner. OF FRED/MELISSA	200	Lin Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - Crack Chase & Grout	Cracks	Grind, grout	715 Melissa	SE.	70	Lin Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - Crack Chase & Grout	Cracks	Qty is the length of the wall	Melissa	Melissa North. Between	300	Lin Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - Crack Chase & Grout	Cracks, spalling	Qty is the length of the wall	Melissa	Melissa Center. Between	300	Lin Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - Crack Chase & Grout	Cracks	Grind, crack chase and fill . BOTH SIDES, qty is 2X	Melissa	Melissa South, newest section of wall. Closer to melissa	500	Lin Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - Crack Chase & Grout	Crack chase and fill		700 Powell		20	Lin Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - Crack Chase & Grout	Crack chase & grind		716 Powell	rear	25	Lin Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - Crack Chase & Grout	Crack chase & fill		720 Powell	rear patio	25	Lin Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - Crack Chase & Grout	Crack chase and tuck point.	2 to 3 ft high wall, qty is the length of entire	Powell	Retaining wall between Powell/ melissa	270	Lin Ft

TASK LIST - PC1106 masonry CMU Repairs, Bartow RAD

Primary	Site	Trade Description	Deficiency	Solution	Addr Street	Location Notes	Qty	Unit
A.3.2.9.03 Repair CMU Walls	481170	CMU - Demo & Replace	Erosion	Repair block wall	205 7th	Driveway	10	Sq Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - Demo & Replace	Remove and replace damaged wall	Approx 3 courses	309 7th	rear @ swale area	60	Sq Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - Demo & Replace	Grind		708 Dolph	rear ret wall	4	Sq Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - Demo & Replace	Remove and replace retaining wall	approx 3x30	736 Dolph	between dolph/powell	90	Sq Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - Demo & Replace	cut / trip hazard - old pipe	Cut pipes flush and patch	Dolph	Retaining wall between powell and dolph	10	Each
A.3.2.9.03 Repair CMU Walls	481170	CMU - Demo & Replace	Cracked wall	Repair	800 Fredricks	Trash area	18	Sq Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - Demo & Replace	cut / trip hazard - old pipe	Cut pipe flush and patch	Fredricks	Retaining wall between dolph and fredricks	10	Each
A.3.2.9.03 Repair CMU Walls	481170	CMU - Demo & Replace	Replace damaged / leaning wall	3 courses high	708 Powell	Retaining g wall	150	Sq Ft
A.3.2.9.03 Repair	481170	CMU - Grind	Grinding and patch	poor workmanship	700 Fredricks	Retaining wall	16	Lin Ft
A.3.2.9.03 Repair	481170	CMU - Grind	Grind smooth	Bad workmanship	716 Powell	rear wall	4	Sq Ft
A.3.2.9.03 Repair	481170	CMU - Grind	Grind smooth	Previously bad	720 Powell	rear wall	4	Sq Ft
A.3.2.9.03 Repair	481170	CMU - Grind	cut / trip hazard - old	Cut metal post flush	Powell	Retaining wall between	10	Each
A.3.2.9.03 Repair CMU Walls	481170	CMU - New Wall	Erosion	new retaining wall. 2 courses down to 1	221 7th	Driveway right side	60	Sq Ft
A.3.2.9.03 Repair	481170	CMU - New Wall	erosion onto driveway	Extend retaining wall	300 Collins	At front porch	24	Sq Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - New Wall	erosion onto driveway	1 more course . Stop at approach	300 Collins	left of driveway	36	Sq Ft
A.3.2.9.03 Repair	481170	CMU - New Wall	Erosion	Extend block wall .	301 Collins	Front porch	18	Sq Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - New Wall	Erosion	Extend block wall . 5 ft slop to 2 courses	301 Collins	Rear patio and storage room	50	Sq Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - New Wall	erosion onto driveway	Extend retaining wall, add 1 course	308 Collins	front porch	54	Sq Ft
A.3.2.9.03 Repair	481170	CMU - New Wall	Erosion	Extend block wall. 2 ft	309 Collins	Front porch	10	Sq Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - New Wall	Erosion onto clothesline area	Extend r the retaining wall . 3 ft high, fade to	320 Collins	Trash area	75	Sq Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - New Wall	Erosion from 723 Melissa	Extend retaining wall. 5 ft high, fade to 1	321 Collins	SE by trash area.	75	Sq Ft

TASK LIST - PC1106 masonry CMU Repairs, Bartow RAD

Primary	Site	Trade Description	Deficiency	Solution	Addr Street	Location Notes	Qty	Unit
A.3.2.9.03 Repair CMU Walls	481170	CMU - New Wall	erosion	Max 4 courses, fade down to one by the	700 Fredricks		160	Sq Ft
A.3.2.9.03 Repair	481170	CMU - New Wall	Fall hazard, wall	Fill in cmu	701 Fredricks	Retaining wall at rear	16	Sq Ft
A.3.2.9.03 Repair	481170	CMU - New Wall	erosion	Extend retaining wall	704 Fredricks		40	Sq Ft
A.3.2.9.03 Repair	481170	CMU - New Wall	erosion onto driveway	Extend retaining wall	708 Fredricks		40	Sq Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - New Wall	erosion onto driveway	Extend retaining wall - 2 courses fade tor one	712 Fredricks		40	Sq Ft
A.3.2.9.03 Repair	481170	CMU - New Wall	erosion onto driveway	Extend retaining wall	720 Fredricks		40	Sq Ft
A.3.2.9.03 Repair	481170	CMU - New Wall	Erosion	Extend retaining wall .	800 Fredricks	NE . CORNER OF	45	Sq Ft
A.3.2.9.03 Repair CMU Walls	481170	CMU - New Wall	Erosion	Extend lock wall towards the west. 2 ft	800 Fredricks	Driveway and trash area	20	Sq Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - Add Course(s)	Erosion	Add two courses to retaining wall	900 Bighorn	Northwest corner	24	Lin Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - Add Course(s)	Erosion	Add one course to retaining wall	902 Bighorn	East side	45	Lin Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - Add Course(s)	Erosion	Add on course	937 Bighorn	Retaining wall between units	45	Lin Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - Add Course(s)	Flooding wash overflows	Add two courses to the top of the existing wall	Zion	South property line behind Zion next to the	600	Lin Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - Crack Chase & Grout	Crack in CMU wall	Grout	2008 Bighorn	Clothesline area . East property line	8	Lin Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - Crack Chase & Grout	Cracks in cmu	Grout	2012 Bighorn	Western property line	5	Lin Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - Crack Chase & Grout	Cracks in wall	Grout	2020 Bighorn	West property line	5	Lin Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - Crack Chase & Grout	Retaining wall damage	Grout	Bighorn	Basketball court	100	Lin Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - Crack Chase & Grout	cracks	Grout	Bighorn	Retaining wall between Big Horn Zion.300 ft	300	Lin Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - Crack Chase & Grout	Cracks	Grout	936 Lassen	Clothesline slab	24	Lin Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - Crack Chase & Grout	Cracks	Grout	900 Zion	retaining wall between Monterey and Bighorn	20	Lin Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - Crack Chase & Grout	Cracks	Grout		South property line behind Zion	840	Lin Ft

TASK LIST - PC1106 masonry CMU Repairs, Bartow RAD

Primary	Site	Trade Description	Deficiency	Solution	Addr Street	Location Notes	Qty	Unit
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - Crack Chase & Grout	Cracks	Grout		East prop line Muriel south of Zion	108	Lin Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - Crack Chase & Grout	Cracks	Grout		North property line on Rimrock	885	Lin Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - Crack Chase & Grout	CMU wall damage	Grout		East Prop Line.Muriel Street between Big	230	Lin Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - Crack Chase & Grout	Cracks, broken blocks	more photos.		East Prop Line.Muriel Street between Big		
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - Crack Chase & Grout	Cracks			East Prop Line. Muriel From Bighorn to	350	
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - Demo & Replace	Retaining wall damage . 2 courses	Replacement	Lassen	Basketball court	40	Sq Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - Demo & Replace	Missing block		916 Zion	South west corner	4	Sq Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - Demo & Replace	Retaining wall is too high kids jump on the	Remove two courses of block	920 Zion	West	60	Sq Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - New Wall	Erosion	Extend existing retaining wall three	937 Bighorn	Clothes line area	30	Sq Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - New Wall	Erosion	New retaining wall . 3 courses	2008 Bighorn	Clothesline area	72	Sq Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - New Wall	Erosion	New retaining wall . 4 ft	2012 Lassen	Clothes line area	200	Sq Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - New Wall	Flooding	new block wall & swale	900 Zion	Western propert border next to field	300	Sq Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - New Wall	Erosion and flooding	Extend retaining wall. 3 courses, fade to one	904 Zion	South west of laundry room	30	Sq Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - New Wall	Erosion	Extend retaining wall, three courses	907 Zion	North west near clothes lines	36	Sq Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - New Wall	Erosion and flooding	Extend existing retaining wall for course or courses feet	908 Zion	South west of building	48	Sq Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - New Wall	Erosion	Extend retaining wall around the corner of	912 Zion	Clothesline slab	75	Sq Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - New Wall	Erosion and flooding flooding	Extend retaining wall three courses feed to	912 Zion	North west corner	30	Sq Ft

TASK LIST - PC1106 masonry CMU Repairs, Bartow RAD

<b>Primary</b>	<b>Site</b>	<b>Trade Description</b>	<b>Deficiency</b>	<b>Solution</b>	<b>Addr Street</b>	<b>Location Notes</b>	<b>Qty</b>	<b>Unit</b>
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - New Wall	Erosion and flooding	Extend retaining wall three courses feet	912 Zion	South west corner of building	36	Sq Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - New Wall	Erosion	Extend retaining wall three courses hi	913 Zion	North west corner by clotheslines	24	Sq Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - New Wall	Erosion	Extend the retaining wall cut down tree	917 Zion	North west corner clothes line area	36	Sq Ft
C.3.2.9.03 Fencing CMU Repairs	481172	CMU - New Wall	Erosion	New wall 5 courses, fade to one	921 Zion	Southeast corner near the pedestrian	150	Sq Ft
C.3.2.9.03 Fencing CMU Repairs	481174	CMU - Crack Chase & Grout	Cracked CMU		1909 Yosemite	Driveway	20	Lin Ft
C.3.2.9.03 Fencing CMU Repairs	481174	CMU - Crack Chase & Grout	wall cracks		1913 Yosemite	Right side of driveway	60	Lin Ft
C.3.2.9.03 Fencing CMU Repairs	481174	CMU - Demo & Replace	Retaining wall broken	Connect the 2 sections together	1916 Yosemite	North side of driveway	16	Sq Ft
C.3.2.9.03 Fencing CMU Repairs	481174	CMU - New Wall	Erosion	Extend retaining wall. 4x16	1920 Yosemite	Southwest retaining wall	64	Sq Ft
C.3.2.9.03 Fencing CMU Repairs	481174	CMU - New Wall	Erosion	Extend retaining wall . 4x16	1921 Yosemite	Clothes line area	64	Sq Ft
C.3.2.9.03 Fencing CMU Repairs	481174	CMU - New Wall	Erosion	Extend retaining wall . 4x16	1928 Yosemite	South west retaining wall	64	Sq Ft